EXHIBIT A TO OFFER TO PURCHASE -- CITY OF MILWAUKEE SCOPE OF WORK

Scope of	Work for Property Loca	ated at:	5338 North 35th Street			
	Property is: Single Fam	ily 🗹 Duple	Other			
Date:	10/11/2018	_	OCCUPIED VACANT			
	this Scope upon visual inspection discovery of conditions that are or		se. City does not warrant content or conclusions, and is not resp s or concems	oonsible for errors,		
			te Essential Repairs and obtain "Essential	Repair Verificat	ion Form"	
			ity's deed to buyer in order to get return of			
Location	Required Work		Note/Comments	Cost		
Entire Building	Structural Violations	n/a □ Yes □	l	\$		
	Defective/Missing HVAC	n/a □ Yes □	1	\$		
	Defective/Missing Plumbing	n/a ☐ Yes □	upper & lower tub faucets and 1st floor lavatory drain piping	\$ 1,100.00		
	Defective/Missing Electrical	n/a ☐ Yes ☐	receptacles, switches, & fixtures and repair wiring at water heater	\$ 1,050.00		
	Defective/Missing Egress	n/a 🗌 Yes 🛭	<u> </u>	\$		
	Defective/Missing Smoke Alarm	n/a ☐ Yes ☐		\$		
	Defective/Missing CO Alarm	n/a ☐ Yes ☐		\$		
	Defective/Missing Roof (Major)	n/a Yes		\$ 11,000.00		
	Missing Window(s)	n/a 🗌 Yes 🛭		\$		
	Other	n/a ☐ Yes ⊡	repair interior walls & ceilings and paint	\$ 5,250.00	Essential Repairs Total	
	Other	n/a ☐ Yes [Remove asbestos wrap from basement. Permit required. Raze Garage (requires permit) or repair to code compliant condition. Repair, replace, or remove defective parking surface	\$ 10,850.00	29,250.00	
Location Site	Condition Report Required Work	n/a □ Yes □	Note/Comments	Cost		
Site	Landscaping Steps/Handrails	n/a Yes		\$		
	Service walks	n/a ∏ Yes ⊡		\$ 1,120.00		
	Fencing	n/a 🗌 Yes 🗆		\$		
	Parking		SEE ESSENTIAL REPAIRS	\$		
	Retaining walls	n/a ☐ Yes ☐		\$		
	Other	n/a Yes		\$		
	Other	n/a ☐ Yes ☐	<u> </u>	\$		
Garage	Singles: repair	n/a □ Yes □		\$		
	Shingles: Roof over existing	n/a ☐ Yes ☐		\$		
	Shingles:Tear off & re-roof	n/a ☐ Yes ☐		\$		
	Gutters/downspouts	n/a Yes	L _{ie}	\$		
	Flashing	n/a Yes		\$		
	Eaves	n/a Yes		\$		
	Siding	n/a Yes	<u> </u>	\$		
	Doors	n/a Yes		\$		
	Windows	n/a Yes	<u></u>	\$		
	Slab	n/a Yes		\$		
	Paint	n/a □ Yes □	1	\$		

Garage (C	on Electrical	n/a Yes 🗌	\$	
_	Other	n/a Yes 🔽 SEE ESSENTIAL RE	EPAIRS \$	
Porches	Roof	n/a Yes	\$	
	Deck-upper	n/a Yes	\$	
	Decklower	n/a Yes	\$	
	Steps/handrails	n/a ☐ Yes ☑ Repair porches, a	s needed \$	1,125.00
	Ceiling	n/a 🗌 Yes 🗌	\$	
	Guardrails	n/a 🗌 Yes 🗌	\$	
	Structural	n/a 🗌 Yes 🗌	\$	
	Paint	n/a 🗌 Yes 🗌	\$	
	Other	n/a Yes 🗆	\$	
House	Chimney	n/a 🗌 Yes 🗌	\$	
	Shingles: repair	n/a Yes	\$	
	Shingles: Roof over existing	n/a 🗌 Yes 🗌	\$	
	Shingles:Tear off & re-roof	n/a 🗌 Yes 🗹 SEE ESSENTIAL F	REPAIRS \$	
	Gutters/downspouts	n/a ☐ Yes ☑	\$	210.00
	Flashing	n/a Yes 🗌	\$	
	Eaves	n/a Yes 🗸	\$	420.00
	Siding	n/a Yes 🗸	\$	750.00
	Storm Doors	n/a Yes 🗸 Repair, replace, or	r remove. \$	265.00
	Prime ("main") Doors	n/a 🗌 Yes 🗌	\$	
	Storm Windows	n/a Yes 🗌	\$	_
	Prime ("main") Windows	n/a ☐ Yes ☑	\$	2,480.00
	Paint	n/a ☐ Yes ☑	\$	1,080.00
	Foundation	n/a Yes 🗸 Tuck point	\$	200.00
	Electrical	n/a Yes	\$	
	Other	n/a Yes 🗸 Bilko door defecti	ive \$	500.00
	Other	n/a Yes	\$	_
	Other	n/a Yes	\$	
	Other	n/a Yes	\$	

37,400.00

Exterior: Estimated Cost:*

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report	_			
Maahaniaal	Unit: Entire unit (single family) Upper unit of duplex			Lower unit of duplex Other	
viecnanicai Heating	Required Work				
	Repair/replace boiler	n/a 🔲	Yes 🗌	==	\$
	Repair radiation	n/a 🔲	Yes 🗌		\$
	Repair/replace furnace	n/a 🔲	Yes 🗌		\$
	Repair ductwork	n/a 🔲	Yes 🗌		\$
	Replace thermostat	n/a 🗌	Yes 🗌		\$
	Repair/replace grilles	n/a 🗌	Yes 🗌		\$
	Tune boiler/furn. insp ht exchange	r n/a 🔲	Yes ✓		\$ 492.00
Electrical	Repair/replace receptacles	n/a 🗌	Yes ☑	SEE ESSENTIAL REPAIRS	\$
	Repair/replace switches	n/a 🗌	Yes ✓	SEE ESSENTIAL REPAIRS	\$
	Repair/replace fixtures	n/a 🔲	Yes ✓	SEE ESSENTIAL REPAIRS	\$
	Install outlets and circuits	n/a 🔲	Yes 🗌		\$
	Install outlets and circuits	n/a 🔲	Yes 🗌		\$
	Install outlets and circuits	n/a 🔲	Yes 🗌		\$
	Install outlets and circuits	n/a 🗌	Yes 🗌		\$
	Upgrade service	n/a 🗌	Yes 🗌		\$
	Other	n/a 🔲	Yes ✓	SEE ESSENTIAL REPAIRS	\$
	Other	n/a 🔲	Yes 🗌		\$
Plumbing	Repair/replace kitchen sink	n/a 🗌	Yes 🗌		\$
	Repair/replace kitchen sink faucet		Yes 🗆		\$
	Repair/replace tub	n/a 🗌	Yes 🗆		\$
	Repair/replace tub faucet	n/a 🗌		SEE ESSENTIAL REPAIRS	\$
	Repair/replace toilet	n/a 🔲	Yes 🗆	_	\$
	Repair/replace lavatory	n/a 🔲	Yes 🗆		\$
	Repair/replace lavatory faucet	n/a 🔲	Yes 🗌		\$
	Repair/replace wash tub	n/a 🔲	Yes 🗌		\$
	Repair/replace wash tub faucet	n/a 🗌	Yes 🗌		\$
	Unclog piping:	n/a 🗌	Yes 🗌		\$
	Repair drain/waste/vent piping	n/a 🗌	Yes 🗸	SEE ESSENTIAL REPAIRS	\$
	Repair water piping	n/a 🗌	Yes 🗌		\$
	Repair/replace water heater	n/a 🗌	Yes 🗌		\$
	Other	n/a 🗌	Yes 🗌		\$
	Other	n/a 🗆	Vas 🗆		\$

Replace broken glass n/a Yes	\$ \$	
	\$	
Repair or replace sash n/a ☐ Yes ☐	Ψ	
Doors		
Repair or replace doors n/a Yes	\$	1,200.00
Repair or repl. locks/latches n/a ☐ Yes ☐ Self Help	\$	
Walls/Ceilings		
Repair or repl. @ defective n/a	\$	
Paint		
Repair or repl. @ defective n/a Yes SEE ESSENTIAL REPAIRS	\$	
Fire Safety	<u></u>	
Install smoke/CO alarm:bsmt. n/a Yes Self Help	\$	
Install smoke/CO alarm: 1st flr. n/a	\$	
Install smoke/CO alarm: 2nd fir. n/a	\$	
Handrails		
Repair/replace defective n/a Yes Self Help Stairs	\$	
Repair defective n/a Yes	\$	
Floors	Ψ	
Repair defective n/a ☐ Yes ☑	\$	2,600.00
Other		
Repair defective wall tile n/a	\$	750.00
Remove asbestos n/a	\$	
n/a 🔲 Yes 🔲	\$	
n/a ☐ Yes ☐	\$	
Interior: Estimated Cost:	\$	5,042.00
	· · · · · · · · · · · · · · · · · · ·	· · · · · ·
Total Exterior and Interior Cost:*	\$	42,442.00

Inspected by: Inspector Gorski Date: 10/11/2018

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

 $\label{eq:local_equation} \mbox{All plumbing, heating, electrical, and structural repairs require permits before work can start.}$

Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

 $[\]mbox{^*}\mbox{average}$ contracted cost. Actual costs may vary. Self help will reduce the amount.